

Caerus Piceance LLC
USA-Piceance Creek F81-18G
Loc ID: 315259



Access road to location



Entrance to location

Caerus Piceance LLC
USA-Piceance Creek F81-18G
Loc ID: 315259



Location entrance sign inaccurate and additional information required when replace.



Inaccurate well name. Sign needs required information when replaced.

Caerus Piceance LLC
USA-Piceance Creek F81-18G
Loc ID: 315259



Sediment migration across location



Sediment migration and erosion leaving location

Caerus Piceance LLC
USA-Piceance Creek F81-18G
Loc ID: 315259



Erosion and sediment migration



Sediment migration leaving location

Caerus Piceance LLC
USA-Piceance Creek F81-18G
Loc ID: 315259



Erosion exiting location



Erosion and sediment exiting location

**Caerus Piceance LLC
USA-Piceance Creek F81-18G
Loc ID: 315259**



Location from Southeast corner



Location from Northeast corner

**Caerus Piceance LLC
USA-Piceance Creek F81-18G
Loc ID: 315259**



Location from Northwest corner



Location from Southwest corner