

**Caerus Piceance LLC**  
**USA-Piceance Creek T73-19G**  
**Loc ID: 316074**



**Additional information required on sign if replaced**



**Entrance to location**






**Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074**



**Unmarked anchor**



**Additional information required on sign if replaced**



Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074



Debris



Debris



Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074



**Debris**



**Open to wildlife**



Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074



**Debris**



**Sediment migration**



**Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074**



**Sediment migration**



**Access road in to location**



**Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074**



**Access road to location**



**Access road to location**



**Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074**



**Access road to location**



**Access road off County Road 3**



**Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074**



**Location from Northwest corner**



**Location from Southwest corner**



**Caerus Piceance LLC  
USA-Piceance Creek T73-19G  
Loc ID: 316074**



**Location from Southeast corner**



**Location from Northeast corner**