

Final Reclamation Inspection

August 1, 2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 305875

Inspection Document #: 697504775

Weld County, CO

NENE Section 30 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: BETZ #30-15
Location ID: 305875



Photo 1. Drone aerial imagery illustrates the access road which has been used for the Croissant 30-12, 30-13 and Betz 30-15 well locations. Red arrows indicate road damages from plugging operations on Betz 30-15 (orange circle).



Photo 2. Photo taken from a portion of the access road, facing Southeast. Photo illustrates road damages from plugging operations.



Photo 3. Photo taken from a portion of the access road, facing Northwest. Photo illustrates road damages from plugging operations.



Photo 4. Photo taken from a portion of the access road, facing East. Photo illustrates road damages from plugging operations.



Photo 5. Photo taken from a portion of the access road, facing East. Photo illustrates road damages from plugging operations.

Inspection Photos
Location Name: BETZ #30-15
Location ID: 305875



Photo 6. Photo taken from the well location, facing East. Photo illustrates an open excavation due to plugging operations. Cattle fencing and netting have been installed. Netting is in need of repair as approximate 10" holes were observed.