

Inspection Photos

Location Name: HSR-Hobe State-63N62W 32NWNE Tank Battery

Location ID: 330074



location



Overgrown Vegetation

Inspection Photos

Location Name: HSR-Hobe State-63N62W 32NWE Tank Battery

Location ID: 330074



August 8, 2023 at 9:17 AM
+40.1876, -104.3462
226° SW
Weld County

Energy & Carbon Management Commission



August 8, 2023 at 9:16 AM
+40.1877, -104.3462
207° SW
Weld County

Energy & Carbon Management Commission

Signs

Overgrown Vegetation

Inspection Photos

Location Name: HSR-Hobe State-63N62W 32NWNE Tank Battery

Location ID: 330074



Overgrown Vegetation



Overgrown Vegetation