

Inspection Photos
Location Name: Killin 16-22-5-45
API Number: 125-10745



1. Well sign at well location.



2. View of Wellhead. Note vegetation.

Inspection Photos
Location Name: Killin 16-22-5-45
API Number: 125-10745




3. Well location overview. Note vegetation.



4. Remote Meter Shed. Note vegetation.

Inspection Photos
Location Name: Killin 16-22-5-45
API Number: 125-10745



5. View of undated Chart in Meter Box at time of inspection.

Omimex Meter Test Report

Well Name Killin 16-22-5-45 Date 7-16-20

Diff. Range 0 to 100 Plate 250

Static Range 0 to 150

Temp Average 60

Chart Read	Differential		Chart Read	Static	
	Found	Left		Found	Left
0	0	0	0	0	
100	100	100	150 (250)	150 (250)	
50	50	50	75 (150)	75 (150)	
0	0	0	0	0	

Inspector [Signature]

6. View of Calibration/Test Log inside Meter Shed at time of inspection.

Inspection Photos
Location Name: Killin 16-22-5-45
API Number: 125-10745



7. View of Produced Water Tank at remote Gas Meter Run. Note vegetation.



8. Additional view of Produced Water Tank. Note vegetation.