

# State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403491777

Receive Date:

Report taken by:

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

### OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	<b>Phone Numbers</b>
Address: <u>1099 18TH STREET SUITE 1500</u>		Phone: <u>(970) 313-5582</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Jason Davidson</u>	Email: <u>ENspillremediationcontractor@pdce.com</u>	Mobile: <u>( )</u>

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 25734 Initial Form 27 Document #: 403185090

#### PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☒ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: \_\_\_\_\_

#### SITE INFORMATION

Yes Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-33831</u>	County Name: <u>WELD</u>
Facility Name: <u>Margil 34A</u>		Latitude: <u>40.273495</u>	Longitude: <u>-104.994305</u>
		** correct Lat/Long if needed: Latitude: _____	Longitude: _____
QtrQtr: <u>NWNW</u>	Sec: <u>34</u>	Twp: <u>4N</u>	Range: <u>68W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>
Facility Type: <u>LOCATION</u>	Facility ID: <u>424006</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>Margil 34A</u>		Latitude: <u>40.273499</u>	Longitude: <u>-104.994301</u>
		** correct Lat/Long if needed: Latitude: _____	Longitude: _____
QtrQtr: <u>NWNW</u>	Sec: <u>34</u>	Twp: <u>4N</u>	Range: <u>68W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

Facility Type: WELL		Facility ID: _____		API #: 123-33834		County Name: WELD	
Facility Name: Margil 34KD		Latitude: 40.273350		Longitude: -104.994213			
		** correct Lat/Long if needed: Latitude: _____		Longitude: _____			
QtrQtr: SWNW	Sec: 34	Twp: 4N	Range: 68W	Meridian: 6	Sensitive Area?	Yes	

Facility Type: WELL		Facility ID: _____		API #: 123-33835		County Name: WELD	
Facility Name: Margil 21-34D		Latitude: 40.273543		Longitude: -104.994334			
		** correct Lat/Long if needed: Latitude: _____		Longitude: _____			
QtrQtr: NWNW	Sec: 34	Twp: 4N	Range: 68W	Meridian: 6	Sensitive Area?	Yes	

Facility Type: WELL		Facility ID: _____		API #: 123-33838		County Name: WELD	
Facility Name: Margil 11-34D		Latitude: 40.273593		Longitude: -104.994362			
		** correct Lat/Long if needed: Latitude: _____		Longitude: _____			
QtrQtr: NWNW	Sec: 34	Twp: 4N	Range: 68W	Meridian: 6	Sensitive Area?	Yes	

Facility Type: WELL		Facility ID: _____		API #: 123-33841		County Name: WELD	
Facility Name: Margil 12-34D		Latitude: 40.273447		Longitude: -104.994275			
		** correct Lat/Long if needed: Latitude: _____		Longitude: _____			
QtrQtr: NWNW	Sec: 34	Twp: 4N	Range: 68W	Meridian: 6	Sensitive Area?	Yes	

## SITE CONDITIONS

General soil type - USCS Classifications SM \_\_\_\_\_ Most Sensitive Adjacent Land Use Agricultural \_\_\_\_\_

Is domestic water well within 1/4 mile? No \_\_\_\_\_ Is surface water within 1/4 mile? Yes \_\_\_\_\_

Is groundwater less than 20 feet below ground surface? No \_\_\_\_\_

### Other Potential Receptors within 1/4 mile

The Margil 34A production facility and wellheads are surrounded by vacant fields in all directions. There are no occupied buildings within a quarter mile of the Site. One unnamed ephemeral drainage is mapped approximately 0.25 miles north of the Site and is tributary to the Thompson River. A freshwater emergent wetland is mapped approximately 300' north of the site. There are no groundwater well permits mapped within a quarter mile of the Site, but groundwater is expected to exist between 26 and 53 ft-bgs based on the closest static water levels reported for groundwater well permit numbers 37681 and 88167. There are no additional sensitive areas, wetlands, or wildlife habitats identified within a quarter mile of the site.

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	SOILS	Not impacted	Confirmation Soil Sampling

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

In accordance with ECOM Rule 911, this form serves as notification for the decommissioning and abandonment of the Margil 34A production facility and associated wellheads and on-location flowlines. The ground and sub-surfaces will be visually inspected for hydrocarbon impacts during equipment decommissioning. Field observations and photo documentation will be recorded in a field inspection form for submittal to the ECOM.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Soil samples will be collected from the surface in cardinal directions of the wellhead and grab soil samples will be collected below and/or adjacent to applicable facility equipment, as defined in the Rule 911.a.(4) guidance document (9/20/21), for field screening purposes. Discrete soil samples will be collected for laboratory analysis either in any area of observed hydrocarbon impacts, or in the sample locations designated by the ECOM. GPS data will be collected for all soil sample locations. Soil samples collected at the tank battery will be submitted for laboratory for analysis of BTEX, naphthalene, TPH (C6-C36), 1,2,4-TMB, and 1,3,5-TMB by EPA Methods 8260B and 8015. Soil samples will be collected adjacent to the wellheads from native material and submitted for laboratory analysis of Organic Compounds in Soil, Soil Suitability, and TPH (C6-C36). See the attached Figure 1 for an illustration of the facility layout and proposed soil sample locations.

### Proposed Groundwater Sampling

- ☒ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

If groundwater is encountered during decommissioning and/or abandonment activities, a grab sample will be collected as soon as practical. If contaminated soil is in contact with groundwater or if free product/hydrocarbon sheen are observed, the release will be reported in accordance with Rule 912.b. Groundwater samples will be submitted for laboratory analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene (TMB), and 1,3,5-TMB by EPA Method 8260.

### Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Discrete soil samples will be collected from the base of the partially buried produced water vessel excavation and excavation sidewall in areas most likely to be impacted and exhibiting the highest field screened VOC concentration. Assessment will be conducted during the removal of the on-location flowlines (estimated to be ~100 feet in length each) and soil samples will be collected below the flowline risers. Samples from the base of the produced water vessel and flowline risers will be submitted for analysis of soil suitability parameters. The flowlines and adjacent sub-surface will be inspected for any visual and olfactory indicators of potential failure and hydrocarbon impacts. Soils will be field screened below the flowline and if suspected impacts are observed, a soil sample will be collected for an initial assessment. Samples will be submitted for laboratory analysis of Organic Compounds in Soil and TPH (C6-C36). GPS data and photo documentation will be recorded.

# SITE INVESTIGATION REPORT

## **SAMPLE SUMMARY**

### **Soil**

Number of soil samples collected 33  
Number of soil samples exceeding 915-1 0  
Was the areal and vertical extent of soil contamination delineated? Yes  
Approximate areal extent (square feet) 0

### **NA / ND**

-- Highest concentration of TPH (mg/kg) 77  
-- Highest concentration of SAR 1.87  
BTEX > 915-1 No  
Vertical Extent > 915-1 (in feet) 0

### **Groundwater**

Number of groundwater samples collected 0  
Was extent of groundwater contaminated delineated? No  
Depth to groundwater (below ground surface, in feet)   
Number of groundwater monitoring wells installed   
Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)   
Highest concentration of Toluene (µg/l)   
Highest concentration of Ethylbenzene (µg/l)   
Highest concentration of Xylene (µg/l)   
Highest concentration of Methane (mg/l)

### **Surface Water**

0 Number of surface water samples collected  
 Number of surface water samples exceeding 915-1  
If surface water is impacted, other agency notification may be required.

## **OTHER INVESTIGATION INFORMATION**

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

Two background soil samples were collected from two separate background borings (BKG02@5 and BKG03@5) to characterize background inorganic concentrations. Samples were collected from areas away from potential sources of impact related to the Site. The background sample locations are displayed on Figure 2.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)  Volume of liquid waste (barrels)

☐ Is further site investigation required?

## **REMEDIAL ACTION PLAN**

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

## **SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Based on site investigation activities and laboratory analytical results for confirmation soil samples collected from the Margil 34A wellheads and production facility, removal of source material is not needed.

## **REMEDICATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Based on site investigation activities and laboratory analytical results for confirmation soil samples collected from the Margil 34A wellheads and production facility, a remediation plan is not needed.

## **Soil Remediation Summary**

☐ In Situ

☐ Ex Situ

Bioremediation ( or enhanced bioremediation )

Excavate and offsite disposal

\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_  
Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

### **Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during facility closure activities.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

#### Approved Reporting Schedule:

☐ Quarterly☐ Semi-Annually☐ Annually☒ Other

#### ☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

#### Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other 

### Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator does not have site-specific financial assurance for this project; however, Operator has inactive well, blanket, and surface bonding including Surety IDs 106077122, 106473808, and 106473820, as well as commercial general liability and/or umbrella/excess insurance meeting the requirements of Rule 705.b. Operator does not anticipate making an insurance claim for this project.

- The project has been completed and no further assessment or remediation is required at this time.

Costs included herein are estimates only and may change over time based on numerous factors. Accordingly, Operator makes no guarantees as to the accuracy of such cost estimates, thus providing an estimate for the next year below.

Operator anticipates the remaining cost for this project to be: \$

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation?

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project?

If YES:

☒ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? Yes

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted?           

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Following facility closure activities, the location was backfilled, compacted, and re-contoured to match pre-existing conditions. The location will be reclaimed in accordance with the ECMC 1004 series rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim ☒ Final

Did the Surface Owner provide the seed mix?           

If YES, does the seed mix comply with local soil conservation district recommendations?           

Did the local soil conservation district provide the seed mix?           

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 09/29/2023

Proposed date of completion of Reclamation. 09/29/2024

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 07/15/2022

Actual Spill or Release date, or date of discovery.           

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/06/2023

Proposed site investigation commencement. 02/06/2023

Proposed completion of site investigation. 08/03/2023

### REMEDIAL ACTION DATES

Proposed start date of Remediation.           

Proposed date of completion of Remediation.           

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

**OPERATOR COMMENT**

In accordance with email correspondence with the ECMC (July 5, 2023), and approved Supplemental Form 27 Document Number 403456194, PDC collected additional confirmation soil samples at soil sample locations PWV02@5, WH01-S@4, WH02-S@4, WH03-S@4, WH04-S@4, and WH05-S@. Samples were submitted for analysis of PAHs by ECMC approved methods.

All analytical results reported for confirmation soil samples mentioned above were reported as below the method detection limit and compliant with their respective Table 915-1 Protection of Groundwater Soil Screening Levels. This data is supplemental to the Facility Closure Investigation and Environmental Report - Margil 34A Tank Battery and Associated Wellheads submitted with Form 27 Document Number 403456194.

Sample location information is provided in Table 1 and the analytical results are summarized in Table 2, Table 3 and Table 4. A general location map is provided on Figure 1. Soil sample, and field screening locations are presented on Figure 2, Figure 3, Figure 4, and Figure 5. The laboratory analytical report is also attached.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jason Davidson

Title: Senior Env. Specialist

Submit Date: \_\_\_\_\_

Email: ENspillremediationcontractor@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 25734

**COA Type****Description**

0 COA	

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

403491787	ANALYTICAL RESULTS
403491788	SOIL SAMPLE LOCATION MAP
403491790	ANALYTICAL RESULTS

Total Attach: 3 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)