

**Inspection Photos**  
**Location Name: Bowman 9-21-5-44**  
**API Number: 125-09513**



**1. Well sign at well location.**



**2. View of Wellhead.**

**Inspection Photos**  
**Location Name: Bowman 9-21-5-44**  
**API Number: 125-09513**




**3. Additional view of Wellhead. Wellhead is leaking gas at cap and packing.**



**4. View of Gas Meter in Meter Shed.**



**Inspection Photos**  
**Location Name: Bowman 9-21-5-44**  
**API Number: 125-09513**



**5. View of Chart that was in Meter Box at time of inspection.**



**6. View of Meter Calibration/Test Log inside Meter Shed at time of inspection.**

**Inspection Photos**  
**Location Name: Bowman 9-21-5-44**  
**API Number: 125-09513**



**7. Location overview. Note vegetation.**



**8. One of two unmarked Deadmen located by Inspector.**