


Inspection Photos
Location Name: Bowman 8-21-5-44
API Number: 125-09515



1. Well sign at well location.



2. View of Wellhead. Note vegetation.

Inspection Photos
Location Name: Bowman 8-21-5-44
API Number: 125-09515



3. View of production related debris left at well site.



4. Twisted Chart found in Meter Box at time of inspection.

Inspection Photos
Location Name: Bowman 8-21-5-44
API Number: 125-09515

Omimex Meter Test Report

Well Name Bowman 8-21-5-44 Date 8-20

Diff. Range 0 to 100 Plate 1250
Static Range 0 to 150
Temp Average 60

Differential		
Chart Read	Found	Left
0	0	0
100	100	100
50	50	50
0	0	0

Static		
Chart Read	Found	Left
0	0	0
150 (250)	150	150 (250)
75 (150)	75	75 (150)
0	0	0

Inspector Coy Kato

2023.08.08 16:21

5. View of Meter Calibration/Test Log in Meter Shed at time of inspection.



6. Location overview. Note vegetation.