

Inspection Photos

Location Name: CUYKENDALL-LAUCK -62N63W 18SENW Tank Battery

Location ID: 317921



Location

Incorrect sign does not reflect current operator

Inspection Photos

Location Name: CUYKENDALL-LAUCK -62N63W 18SENW Tank Battery

Location ID: 317921



Overgrown vegetation

Overgrown vegetation

Inspection Photos

Location Name: CUYKENDALL-LAUCK -62N63W 18SE14 Tank Battery

Location ID: 317921



Overgrown vegetation

Overgrown vegetation

Inspection Photos

Location Name: CUYKENDALL-LAUCK -62N63W 18SE1W Tank Battery

Location ID: 317921



Overgrown vegetation



Unused equipment

Inspection Photos

Location Name: CUYKENDALL-LAUCK -62N63W 18SE14 Tank Battery

Location ID: 317921



Overgrown vegetation



Overgrown vegetation


Inspection Photos

Location Name: CUYKENDALL-LAUCK -62N63W 18SEW Tank Battery

Location ID: 317921



Overgrown vegetation



Weathered NFA placard/ Missing capacity label