

**Inspection Photos**  
**Location Name: Mart-62N62W 27NWNW Tank Battery**  
**Location ID: 318537**



**Production Equipment & Overgrown vegetation**

**Gas meter run and overgrown vegetation**

# Inspection Photos

Location Name: Mart-62N62W 27NWNW Tank Battery

Location ID: 318537



August 10, 2023 at 10:22 AM  
+40.1150, -104.3171  
123° SE  
Weld County  
Energy & Carbon Management Commission

**Not legible meter card**



August 10, 2023 at 10:14 AM  
+40.1150, -104.3171  
42° NE  
Weld County  
Energy & Carbon Management Commission

**Disconnected sales line**

# Inspection Photos

Location Name: Mart-62N62W 27NWNW Tank Battery

Location ID: 318537



August 10, 2023 at 10:15 AM  
+40.1148 -104.3172  
266° W  
Weld County  
Energy & Carbon Management Commission



August 10, 2023 at 10:15 AM  
+40.1148 -104.3172  
207° SW  
Weld County  
Energy & Carbon Management Commission

**Overgrown vegetation**

**Incorrect operator sign & overgrown vegetation**

# Inspection Photos

Location Name: Mart-62N62W 27NWNW Tank Battery

Location ID: 318537



Erosion

Erosion

## Inspection Photos

Location Name: Mart-62N62W 27NWNW Tank Battery

Location ID: 318537



**Overgrown vegetation**

