

Interim Reclamation and Stormwater Inspection

August 3, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462908

Inspection Document #: 697504790

Weld County, CO

NESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 1. Photo taken from the southeastern location, facing East. Photo illustrates interim reclamation areas have been reseeded; however, erosion that was previously observed is in need of repair.



Photo 2. Close up photo taken of the erosion needing repair.



Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 3. Photo taken from the southeastern location, facing North. Photo illustrates interim reclamation areas have been reseeded. There was some desirable germination observed; however, Staff is not comfortable putting this In-Process until further germination of desirable species is established.



Photo 4. Photo taken from the southwestern location, facing North. See comments under Photo 3.



Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 5. Photo taken from the southwestern location, facing South. See comments under Photo 3.



Photo 6. Photo taken from the topsoil stockpile, facing East. Photo illustrates the topsoil stockpile has been reseeded; however, Staff is not comfortable putting this In-Process until further germination of desirable species is established.

.

