

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 8/14/2023



SE Corner of Location – Photo #05771



NE Corner of Location – Photo #05772

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 8/14/2023



NW Corner of Location – Photo #05773



SW Corner of Location – Photo #05774

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 8/14/2023



Aug 14, 2023 at 10:32:31



Aug 14, 2023 at 10:34:18

Wellhead – Photo #05776

Separator – Photo #05779

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 8/14/2023



Tank Battery – Photo #05778



Debris on West Side of Pad – Photo #05775

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 8/14/2023



Debris Behind Separator – Photo #05780