

Inspection Photos

8/14/2023

Operator: GENESIS GAS & OIL COLORADO LLC
- 10384

Location Number: 316579
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579




Photo 1: Photo taken with a sUAS. Photo shows that a spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location and traveled off-site to the northwest along and on the lease road (red arrows); spill traveled approximately 1,000 feet from point of release to approximate end point. Photo also shows unused equipment/debris improperly stored on the Location (yellow arrows).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 2: Photo taken with a sUAS. Photo shows that a spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location and traveled off-site to the northwest along and on the lease road; spill traveled approximately 1,000 feet from point of release to approximate end point. Photo also shows unused equipment/debris improperly stored on the Location (yellow arrows).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 3: Photo taken with a sUAS. Photo shows that a spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location and traveled off-site to the northwest along and on the lease road; spill traveled approximately 1,000 feet from point of release to approximate end point.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 4: Photo taken with a sUAS. Photo shows that a spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location and traveled off-site to the northwest along and on the lease road (red arrows); spill traveled approximately 1,000 feet from point of release to approximate end point.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 5: Photo taken with a sUAS. Photo shows that a spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location and traveled off-site to the northwest along and on the lease road; spill traveled approximately 1,000 feet from point of release to approximate end point.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 6: Photo taken with a sUAS. Photo shows that a spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location and traveled off-site to the northwest along and on the lease road; spill traveled approximately 1,000 feet from point of release to approximate end point.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579




Photo 7: Photo taken with a sUAS. Photo shows that a spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location and traveled off-site to the northwest along and on the lease road (red arrows); spill traveled approximately 1,000 feet from point of release to approximate end point.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 8: Degradation on slopes/interim areas due to spill/release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 9: Degradation on slopes/interim areas due to spill/release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 10: Photos taken from the west end of the Location, facing northeast and east. Photos provide overview of the Location. Photo also shows that stormwater, erosion and vehicle tracking control measures are missing or insufficient; Working pad lacks stabilization- rutting/tracking observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 11: Photo taken from the west end of the working pad surface, facing north. Photo shows spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location and traveled off-site.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 12: Photo shows spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 13: Photo shows spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 14: Photo shows spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



August 14, 2023

Photo 15: Photo shows spill/release of E&P waste fluids originating at the wellhead has impacted large areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GENESIS GAS & OIL COLORADO
Location Number: 316579



Photo 16: Photo taken from the access road north of the Location, facing south. Photo shows approximate end point of the spill/release, ~1,000 feet from the wellhead (red arrow)



Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



August 14, 2023

Photo 17: Photo shows spill/release originating from the well head had traveled and impacted areas along the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 18: Photo shows spill/release originating from the well head had traveled and impacted areas along the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 19: Photo shows degradation along the interim areas/slopes of the Location due to the spill/release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 20: Unused cable and pipe improperly stored on the interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GENESIS GAS & OIL COLORADO LLC - 10384

Location Number: 316579



Photo 21: Sucker rod stored next to wellhead; this is considered unused equipment subject to Rule 606 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources