

# Final Reclamation Inspection

July 15, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 305953

Inspection Document #: 701900989

NENE Section 33 T7N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Alm 41-33  
Location ID: 305953



**Photo 1.** 2023 aerial imagery of the well pad and tank battery (north is up).



**Photo 2.** Overview photo of the well pad taken at ground level from the southern edge facing north. Note: well pad falls within an active cattle pasture. Fence was constructed after plugging of the well.



**Photo 3.** Overview photo of the well pad taken at ground level from the northern edge facing south. Note: well pad appears consistent with adjacent reference area (see photo 4).

Inspection Photos  
Location Name: Alm 41-33  
Location ID: 305953



**Photo 4.** Well pad reference area (east of the well pad).



**Photo 5.** Overview photo of the tank battery taken at ground level from the southern edge facing north.

Inspection Photos  
Location Name: Alm 41-33  
Location ID: 305953



**Photo 6.** Cardinal photos taken from the middle of the tank battery.  
Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Alm 41-33  
Location ID: 305953



**Photo 7.** Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west.



**Photo 8.** DCP midstream riser remains at the tank battery location.