

Final Reclamation Inspection

July 15, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 327289

Inspection Document #: 701900995

SESE Section 28 T4N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lorenz 44-28
Location ID: 327289



Photo 1. 2023 aerial imagery of the well pad and tank battery (north is up). Note: tank battery falls on the active Hunt Federal production facility, location ID 442636.




Photo 2. Overview photo of the well pad and tank battery taken with a drone from directly above the disturbance. Note: well pad appears consistent with adjacent crop reference area.

Inspection Photos
Location Name: Lorenz 44-28
Location ID: 327289



Photo 3. Overview photo of the tank battery taken at ground level from the southern edge facing north east.