

# Final Reclamation Inspection

August 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 307179

Inspection Document #: 701901046

NESE Section 21 T6N R66W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources


Inspection Photos  
Location Name: Laune 44-25  
Location ID: 307179



**Photo 1.** 2016 aerial imagery of the well pad, access road and associated tank battery (north is up).




Inspection Photos  
Location Name: Laune 44-25  
Location ID:307179



**Photo 2.** Overview photo of the well pad and access road taken from the southern edge facing north using a drone. Photo shows that the well pad and access road appear consistent with the adjacent reference area.





**Photo 3.** Overview photo of the tank battery taken from the southern edge facing north using a drone. Photo shows that the eastern edge of the tank battery has stunted crop growth that does not appear consistent with the adjacent crop reference area.





**Photo 4.** Ground photo of the tank battery taken from the eastern edge facing west.