

# Final Reclamation Inspection

August 2nd, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 331302

Inspection Document #: 701901050

NESE Section 12 T6N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Williamson 43-12  
Location ID: 331302



**Photo 1.** 2023 aerial imagery of the well pad (north is up).

Inspection Photos  
Location Name: Williamson 43-12  
Location ID:331144



**Photo 2.** Photo of the well pad/tank battery crop field that has already been harvested.