

Photo Log

Blue Chip Oil, Inc. – #8840

Shannon Roberts Produced Water Tank Replacement

February 2023

Pre-Removal During Initial Excavation and Hydrovac





After Removal of the Water Tank



Sample Locations






North Wall Sample

East Wall Sample

Background Sample Location



Background Sample

Pad after Gypsum Application, and Backfill, Prepared for new Tank

