



# Photo Log

Blue Chip Oil, Inc. – #8840  
Shannon Roberts Produced Water Tank Replacement  
July 2023

South Wall Bored to 3 ft and sampled.



East Wall Bored to 3 ft and sampled.



North Wall Bored to 3 ft and sampled.



West Wall Bored to 3 ft and sampled.



Floor Bored under tank to 4.5 ft TVD and sampled.

