


Inspection Photos  
Location Name: Bennett State 9-16-5-45  
API Number: 125-09728



1. Well sign broken out of bracket. Note vegetation.



2. View of Wellhead. Note vegetation.

**Inspection Photos**  
**Location Name: Bennett State 9-16-5-45**  
**API Number: 125-09728**



**3. View of Wellhead with tubing approximately 12' out of well cap. Note vegetation.**



**4. Cement pad left after Pump Jack removal and production related debris. Note vegetation.**

**Inspection Photos**  
**Location Name: Bennett State 9-16-5-45**  
**API Number: 125-09728**




**5. Additional unused equipment left at location.**



**6. Well location overview.**

Inspection Photos  
Location Name: Bennett State 9-16-5-45  
API Number: 125-09728



7. Well sign at remote Gas Meter Run.




8. Remote Meter Shed. Note vegetation.

**Inspection Photos**  
**Location Name: Bennett State 9-16-5-45**  
**API Number: 125-09728**



**9. Undated Chart in Meter Box at time of inspection.**



**10. Meter Calibration/Test Log inside Meter Shed at time of inspection.**