


## Inspection Photos

Location Name: Bennett State 16-16-5-45

API Number: 125-09855



1. Well sign at well location.



2. View of Wellhead. Note Vegetation.



**Inspection Photos**  
**Location Name: Bennett State 16-16-5-45**  
**API Number: 125-09855**



**3. Production related debris under noted vegetation at well site.**




**4. Well location overview. Note vegetation.**

## Inspection Photos

Location Name: Bennett State 16-16-5-45

API Number: 125-09855



5. Well sign at remote gas meter run.



6. View of remote meter shed. Note vegetation.



**Inspection Photos**  
**Location Name: Bennett State 16-16-5-45**  
**API Number: 125-09855**



**7. View of gas meter run inside meter shed.**



**8. Undated Chart in Meter Box at time of inspection.**

**Inspection Photos**  
**Location Name: Bennett State 16-16-5-45**  
**API Number: 125-09855**

Ominex Meter Test Report

Well Name: Bennett 16-16-5-45 Date: 7-15-20

Diff. Range: 0 to 100 Static Range: 0 to 150 Plate: 250

Temp Average: 80

Differential			Static		
Chart Read	Found	Left	Chart Read	Found	Left
0	0	0	0	0	0
100	100	100	150 (250)	150	150 (250)
50	50	50	75 (150) str	75	75 (150) str
0	0	0	0	0	0

Inspector: [Signature]

2023.08.10 12:40

**9. Meter Calibration/Test Log inside meter shed at time of inspection.**



**10. View of well inlet valve into remote meter shed.**