

## Inspection Photos

Location Name: Bennett State 1-16-5-45

API Number: 125-09517



1. Well sign at well location. Note vegetation.



2. Wellhead. Note vegetation and production related debris in background.



**Inspection Photos**  
**Location Name: Bennett State 1-16-5-45**  
**API Number: 125-09517**




**3. Cement pad left at well site after Pump Jack removal.**




**4. Well location overview. Note vegetation.**

**Inspection Photos**  
**Location Name: Bennett State 1-16-5-45**  
**API Number: 125-09517**



**5. Well sign at remote Meter Shed.**



**6. Undated Chart in Meter Box at time of inspection.**



**Inspection Photos**  
**Location Name: Bennett State 1-16-5-45**  
**API Number: 125-09517**

Omimex Meter Test Report

Well Name Bennett 1-16-5-45 Date 7-16-20

Diff. Range 0 to 100 Static Range 0 to 150 Plate 1500

Temp Average 60

Differential		
Chart Read	Found	Left
0	0	0
100	100	100
50	50	50
0	0	0

Static		
Chart Read	Found	Left
0	0	0
150 (250)	150	150 (250)
75 (±50) 150	75	75 (±50) 150
0	0	0

Inspector [Signature]

2023.08.10 13:32

**7. Meter Calibration/Test Log inside Meter Shed at time of inspection.**



**8. Remote Gas Meter Run overview. Note vegetation.**