

Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520



Photo 1 – Pumping Unit



Photo 2 – Stained Soil at Gear Box

Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520



Photo 3 – Labels have faded no longer visible



Photo 4 – Wellhead

Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520



Photo 5 – Tank Battery



Photo 6 – Tank Battery Sign



Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520



Photo 7 – Pit Area



Photo 8 – Skim Tanks

Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520



Photo 9 – Heater Treater



Photo 10 – Tank Labels missing

Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520



Photo 11 – Weeds



Photo 12 – Weeds