

Inspection Photos
Location Name: Dunbar 1
Location ID: 305616



Photo 1 – Well Sign



Photo 2 – Electrical Motor

Inspection Photos
Location Name: Dunbar 1
Location ID: 305616



Photo 3 – Stained Soil at Gear Box



Photo 4 – Wellhead