

**Inspection Photos**  
**Location Name: Dunbar 1 Tank Battery**  
**Location ID: 474965**



**Photo 1 – Tank Battery – Labels have faded no longer visible**

**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: Dunbar 1 Tank Battery**  
**Location ID: 474965**



**Photo 3 – Heater Treater and Propane Tanks**



**Photo 4 – Pit Area**

Inspection Photos  
Location Name: Dunbar 1 Tank Battery  
Location ID: 474965



Photo 5 – Water Tank missing NFPA Label and Crude Oil Tank Content and Capacity



Photo 6 – Tank Battery Sign