

Inspection Photos
Location Name: Dugan Tiffany 1
Location ID: 067-06498



Photo #1. Weeds around wellhead.

Photo #2. Weeds around separator.

Inspection Photos
Location Name: Dugan Tiffany 1
Location ID: 067-06498



Photo #3. Weeds on and within tank containment berm



Photo #4. Unused muffer hoses on ground.

Inspection Photos
Location Name: Dugan Tiffany 1
Location ID: 067-06498



Photo #5. Overview of well location.



Photo #6. View of offsite meterhouse.