

Inspection Photos

API: 071-09021

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09021 | Date: 8/16/2023

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 071-09021 | Date: 8/16/2023

Inspection Photos



Photo 2. Facing toward the well..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09021 | Date: 8/16/2023

Inspection Photos



Photo 3. There are oily fluids in the engines skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09021 | Date: 8/16/2023

Inspection Photos



Photo 4. Facing southwest at the location. The perennial vegetation is well established throughout the location.

