

Inspection Photos
Location Name: Bledsoe 4-26-5-45
API Number: 125-09611



1. Well sign at well location.



2. View of repaired Wellhead with bent tubing joint removed.

Inspection Photos
Location Name: Bledsoe 4-26-5-45
API Number: 125-09611



3. View of Cement Pad and production related debris. Bent tubing removed from well is laying on cement pad.



4. Well location overview.