

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N31NE Pad**  
**Location ID: 324115**



**Photo # 6065 From entrance to location**



**Photo # 6066 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N31NE Pad**  
**Location ID: 324115**



**Photo # 6067 Location**



**Photo # 6068 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N31NE Pad**  
**Location ID: 324115**



**Photo # 6076 Hole in liner/liner needs maintenance**



**Photo # 6077 Hole in liner/liner needs maintenance**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N31NE Pad**  
**Location ID: 324115**



**Photo # 6078 Hole in liner/liner needs maintenance**



**Photo # 6079 Hole in liner/liner needs maintenance**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N31NE Pad**  
**Location ID: 324115**



**Photo # 6082 Hole in liner/liner needs maintenance**



**Photo # 6083 Hole in liner/liner needs maintenance**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N31NE Pad**  
**Location ID: 324115**



**Photo # 6084 Hole in liner/liner needs maintenance**



**Photo # 6085 Hole in liner/liner needs maintenance**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N31NE Pad**  
**Location ID: 324115**



**Photo # 6086 Hole in liner/liner needs maintenance**




**Photo # 6087 Hole in liner/liner needs maintenance**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N31NE Pad**  
**Location ID: 324115**



**Photo # 6089 Hole in liner/liner needs maintenance**



**Photo # 6090 Hole in liner/liner needs maintenance**