

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/21SWNE

Location ID: 324467

Date: 8/17/2023



NE Entrance to Location – Photo #05968



SE Corner of Location – Photo #05969

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/21SWNE

Location ID: 324467

Date: 8/17/2023



SW Corner of Location – Photo #05970



Wellhead – Photo #05971

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/21SWNE

Location ID: 324467

Date: 8/17/2023



Separator – Photo #05974



Tank Battery – Photo #05973

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/21SWNE

Location ID: 324467

Date: 8/17/2023



**Rill Erosion on Access Road – Photo #05977**



**Rill Erosion on Access Road – Photo #05978**

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/21SWNE

Location ID: 324467

Date: 8/17/2023



**Rill Erosion on Lease Road – Photo #05980**



**Rill Erosion on Lease Road – Photo #05981**

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/21SWNE

Location ID: 324467

Date: 8/17/2023



**Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05917**



**Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05920**

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/21SWNE

Location ID: 324467

Date: 8/17/2023



**Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05921**



**Lease Road Degradation at Clear Fork Crossing – Photo #05923**