

Inspection Photos  
Maralex Gosney 1  
API 067-06570



**Photo #1. Overview of well location.**



**Photo #2. Weeds around wellhead.**

Inspection Photos  
Maralex Gosney 1  
API 067-06570



Photo #3. View of wellhead sign mounted on separator.

