

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6365 From entrance to location



Photo # 6366 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad

Location ID: 334157



Photo # 6367 Location



Photo # 6368 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6370 Location



Photo # 6371 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad

Location ID: 334157



Photo # 6374 Wildlife BMP's need maintenance



Photo # 6377 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6378 Debris



Photo # 6388 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6392 Debris



Photo # 6382 Tank/label missing required information



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad

Location ID: 334157



Photo # 6383 Tank/label missing required information



Photo # 6384 Tank/label missing required information



Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6385 Tank/label missing required information



Photo # 6386 Stained gravel in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6387 Stained gravel in secondary containment



Photo # 6393 Stained soils & gravel

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6389 Unused equipment



Photo # 6390 Unused equipment

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad

Location ID: 334157



Photo # 6391 Open ended load line



Photo # 6402 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad

Location ID: 334157



Photo # 6394 Hole in liner/liner needs maintenance



Photo # 6396 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad

Location ID: 334157



Photo # 6398 Holes in liner/liner needs maintenance



Photo # 6399 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad

Location ID: 334157



Photo # 6400 Hole in liner/liner needs maintenance



Photo # 6401 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157




Photo # 6429 Debris



Photo # 6430 Debris