

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



**Location Overview: Location is within Black Bear Habitat area
& in close proximity to High Priority/NSO Habitat areas.
Location is approximately 196 yards from Pete & Bill Creek.
Section/Township/Range: 7 8S95W**



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



**Photo # 6404 Erosion & transport of sediment onto location
(SW corner of location)**



Photo # 6418 Erosion/tunnel erosion (NE corner of location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6419 Erosion/tunnel erosion (NE corner of location)



Photo # 6420 Erosion/tunnel erosion (NE corner of location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6422 Erosion/tunnel erosion (NE corner of location)



Photo # 6431 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6432 Lack of stabilization/compaction



Photo # 6433 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6435 Lack of stabilization/compaction



Photo # 6436 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6437 Lack of stabilization/compaction



Photo # 6440 Ditch on spur road & BMP's need maintenance

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6445 Ditch on spur road & BMP's need maintenance



Photo # 6446 Ditch on spur road & check dams need maintenance

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 7G Pad
Location ID: 334157



Photo # 6447 Ditch on spur road & check dams need maintenance



Photo # 6448 Ditch on spur road & check dams need maintenance