



99999999

COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	

API No. 05- 009 - 5327	LEASE NAME: SCHWEIZER #1-23
LOCATION: NENE23-335-43W	OPERATOR: McBRIDE
DATE: 1-13-97	INSPECTOR: R. VanSickle
Insp. Type: HR	Insp. Status: PA
PA: (Y) N	Pass/Fail: (P) F
Viol.: Y (N)	NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	Reclaimed, farmed, grass.	↘
Miscellaneous		

CORRECTIVE ACTION REQUIRED: None.	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site



00640112