

Inspection Photos
Location Name: CAERUS PICEANCE LLC D24W Pad
Location ID: 323904



Photo # 6956 From entrance to location



Photo # 6957 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D24W Pad
Location ID: 323904



Photo # 6960 Location



Photo # 6961 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D24W Pad
Location ID: 323904



Photo # 6963 Location



Photo # 6966 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC D24W Pad

Location ID: 323904



Photo # 6968 Open ended load line



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources