



Maralex Mollie Corynne 33-7-2 pad

067-09925 and 067-08800

Photo doc 2

8/18/23



08.18.2023



Tank condition, no contents labeling
or placards, float gauges indicate
mostly full

08.18.2023



08.18.2023



08.18.2023

Vehicle tracking mud from location on
county road



08.18.2023



08.18.2023



08.18.2023



08.18.2023



PEUGOT
AREA PRIVADA
ENTRE ÚNICAMENTE
CON PERMISO
UNICO
CONFINED SPACE
ENTER BY
PERMIT ONLY

08.18.2023



08.18.2023



08.18.2023

Tank integrity issues, leaking fluid at
seam





Drilling fluid off pad



Drilling fluid off pad

08.18.2023



08.18.2023



Oil mixing with fluids

08.18.2023



Oil and drilling fluids outside of
trenches



08.18.2023



No spill prevention measures on
portable toilets



Drilling fluids off location, going onto
hay field

08.18.2023





08.18.2023

Spot 64.8 °F
Box
Avg. 84.6

121



08/18/23 12:24 PM _ Infrared fluid level of tanks

62.1

Spot 65.7 °F
Box
Avg. 74.1

106




08/18/23 12:25 PM

62.4

Spot 102
Box
Avg. 79.7

°F

111



 **FLIR**

08/18/23 12:25 PM

63.0