

Inspection Photos

Location Name: Vera-63N61W 5NWSW Tank Battery

Location ID: 318556



Tank Battery

Overgrown Vegetation & Weathered Berms

Inspection Photos
Location Name: Vera-63N61W 5NWSW Tank Battery
Location ID: 318556



Overgrown Vegetation & Weathered Berms

Overgrown Vegetation & Weathered Berms

Inspection Photos

Location Name: Vera-63N61W 5NWSW Tank Battery

Location ID: 318556



Production Equipment & Overgrown Vegetation

Overgrown Vegetation

Inspection Photos
Location Name: Vera-63N61W 5NWSW Tank Battery
Location ID: 318556



Overgrown Vegetation

Overgrown Vegetation