

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)



99999999

Well Name MOYBERRY #1 API Number 05-009-6390
Operator ANTELOPE Permit # 83 1423
Location NE NE 4 34S 41W County BACS
Field _____ Inspector SHELTON

AL/PA/DA ☒ Inspection Results: Well Status:
Pass ☒ Y Fail(N) _____ Date 2/25/93 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA ☒ Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes ☒ No _____ Pits Backfilled: Yes ☒ No _____
Material Buried: Yes _____ No _____ N/A ☒ Site Clean: Yes ☒ No _____
Bond Release OK: Yes ☒ No _____ Fed _____ Hole Marker: Yes _____ No ☒

Date of Safety/Status Inspection 2/25/93

Comments: OLD DA / SITE RESTORED / STUBBLE



00632025

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____