

Operator: 8 NORTH

Location Name: BASHOR PC GQ 15-13

Loc ID: 461104

Inspection: 696305238



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Weeds on Lease Road, see photos. Comply with Rule 606.

CA Resolution: Operator has reported and provided photo evidence that the identified weeds have been addressed and cleared to comply with Rule 606.



Exhibit A

CA: 24 Hour Contact Number NOT Current; see photos. Install sign to comply with Rule 605.e.

CA Resolution: Field has reported and provided photo evidence that the 24 hour contact number has been successfully updated to comply with Rule 605.e.



Exhibit A



Exhibit B



Exhibit C

CA: Tumbleweed Debris in and around Tank Berm; see photos. Comply with Rule 606

CA Resolution: Operator has reported and provided photo evidence that the identified debris at various locations has been cleared from to comply with Rule 606.