

Operator: 8 NORTH

Location Name: BASHOR PC GQ 15-13

Loc ID: 417826

Inspection: 696305236



Exhibit A



Exhibit B



Exhibit C

CA: Weeds on Lease Road, see photos. Comply with Rule 606.

CA Resolution: Operator has reported and provided photo evidence that the identified weeds have been addressed and cleared to comply with Rule 606.