

WELL SITE INSPECTION FC
(DRILLING AND PLUGGING,



Well Name Cogburn 1-21 API Number 05 - 009 - 5096
Operator Horizon O&G Permit # _____
Location NWSE 21-335-42W County Baca
Field _____ Inspector Binkley

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) _____ Fail(N) _____ Date _____ ND _____ DG _____ WO _____ PR _____ SI _____ TA X

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes _____ No _____ Pits Backfilled: Yes _____ No _____
Material Buried: Yes _____ No _____ N/A _____ Site Clean: Yes _____ No _____
Bond Release OK: Yes _____ No _____ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection 2-15-91

Comments: Shut in w/ valve on tbq, Sep. meter, 1-200 tank. Sign.

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____

NGPA
Filing Fee

Date Check Received

Oct. 29, 1979

3/1/79

FILING NO(S).

79-494

And/Or

WELL NAME(S)

Cogburn #1-21

Date of Check

10/24/79

Check #

1687

Amt. \$

700.⁰⁰

Name of Company

Bruce Calder, Inc.

Maker of Check

Same

Bank Check Issued On

Republic Natl. Bank
(Dallas, Tx)