

WELL SITE INS  
(DRILLING AND PLUGGING)



(C)

Well Name Cogburn 1-21 API Number 05-009-5096  
Operator Horizon Permit # -  
Location NWSE 21-335-42W County Bacon  
Field \_\_\_\_\_ Inspector Smiley

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) \_\_\_\_\_ Fail(N) \_\_\_\_\_ Date \_\_\_\_\_ ND \_\_\_\_\_ DG \_\_\_\_\_ WO \_\_\_\_\_ PR \_\_\_\_\_ SI \_\_\_\_\_ TA X

Date of Inspection Before/During Drilling \_\_\_\_\_

Surf. Csg. Size \_\_\_\_\_ Setting Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_ WOC time \_\_\_\_\_  
Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Stage Tool Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_

Date of Inspection Before/During/After Completion \_\_\_\_\_

Prod. Csg. Set? \_\_\_\_\_ Completion Rig/Activity \_\_\_\_\_  
Drilling Pits: Closed \_\_\_\_\_ Open \_\_\_\_\_ Wellhead Installed: \_\_\_\_\_ Sign: Yes \_\_\_\_\_ No \_\_\_\_\_  
Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: \_\_\_\_\_ Prod. Tanks: ( ) \_\_\_\_\_ BBLs  
Equipment \_\_\_\_\_ Meter Run: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bradenhead Press: \_\_\_\_\_ Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

AL/PA/DA Inspection

Date Plugged: VP 71791 Date Permit Expired: \_\_\_\_\_  
Hole Plugged: Yes \_\_\_\_\_ No X Pits Backfilled: Yes ✓ No \_\_\_\_\_  
Material Buried: Yes \_\_\_\_\_ No X N/A \_\_\_\_\_ Site Clean: Yes \_\_\_\_\_ No X  
Bond Release OK: Yes \_\_\_\_\_ No X Fed \_\_\_\_\_ Hole Marker: Yes \_\_\_\_\_ No X

Date of Safety/Status Inspection 81491

Comments: flow test 300 b fault (HOR), risers, oily site  
near farmers grain yard. Muddy access. Fenced.

Violations: Yes \_\_\_\_\_ No X Notice Sent: Yes \_\_\_\_\_ No \_\_\_\_\_ Date Sent: \_\_\_\_\_