

Inspection Photos

Location Name:

HSR-Cervi Federal-63N62W 29NENW Tank Battery

Location ID: 330614



Tank Battery



Overgrown Vegetation

Inspection Photos

Location Name:

HSR-Cervi Federal-63N62W 29NENW Tank Battery

Location ID: 330614



Production Equipment



Overgrown Vegetation



Inspection Photos

Location Name:

HSR-Cervi Federal-63N62W 29NENW Tank Battery

Location ID: 330614



Overgrown Vegetation



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources