

## Inspection Photos

Location Name: HSR-Cervi/ Fed-63N62W 29NESW Tank Battery

Location ID: 330188



**Tank Battery**

**Production Equipment**

## Inspection Photos

Location Name: HSR-Cervi/ Fed-63N62W 29NESW Tank Battery

Location ID: 330188



**Overgrown Vegetation**



**Tumble Weeds**