

Inspection Photos

8/28/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 311692

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 311692



Photo 1: Photos 1-3 show erosion degradation recurring on the slopes on the south end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 311692



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 311692



Photo 3: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 311692



Photo 4: Photos 4-5 show Musk thistle establishing throughout the northern interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 311692



Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources