

# Inspection Photos

8/28/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 334085

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 334085



**Photo 1:** Overview of the WPS, facing northeast and southeast.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334085



**Photo 2:** Unused and/or empty containers improperly stored within the secondary containment berm of the tank battery facility.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 334085



**Photo 3:** Photo left example of stained soils observed at the tank battery facility. Photo right example showing label information missing, or in disrepair at tanks.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334085



**Photo 4:** Photos taken from the interim areas on the east/southeast end of the Location. Vegetation within these areas is predominantly desirable perennial vegetation; areas are progressing towards 1003 standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334085



**Photo 5:** Photos taken from the southwestern / western interim areas of the Location. Vegetation observed is predominantly undesirable weedy plant species such as Tumble Mustard, Prickly lettuce, cheatgrass, etc... These areas are not progressing towards 1003 standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources