

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad

Location ID: 415673



Photo # 6611 From entrance to location



Photo # 6612 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad

Location ID: 415673



Photo # 6614 Location



Photo # 6615 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad

Location ID: 415673



Photo # 6617 Location



Photo # 6618 Wildlife netting needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad

Location ID: 415673



Photo # 6629 Open ended piping/wildlife hazard



Photo # 6630 Open ended piping/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad

Location ID: 415673



Photo # 6671 Unmarked container/unknown contents



Photo # 6674 Tank/label missing required information

Inspection Photos
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 6675 Tank/label missing required information

Photo # 6682 Tank/label missing required information

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad

Location ID: 415673



Photo # 6676 Open ended load line



Photo # 6677 Containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad

Location ID: 415673



Photo # 6681 Debris



Photo # 6666 Debris