

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 129-29 Pad

Location ID: 335243



Photo # 6994 From entrance to location



Photo # 6995 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 129-29 Pad

Location ID: 335243



Photo # 7000 Location



Photo # 7005 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 129-29 Pad

Location ID: 335243



Photo # 7007 Stained soils & gravel



Photo # 7008 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 129-29 Pad

Location ID: 335243



Photo # 7010 Stained soils & gravel