

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**Location Overview: Location is within Black Bear Habitat area  
& in close proximity to High Priority/Density Habitat areas.**

**Section/Township/Range: 1 8S96W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



Aug 21, 2023 at 10:56:12 AM  
CO

**Photo # 6832 Erosion & transport of sediment across spur road to location & into a vegetated area**



Aug 21, 2023 at 10:56:39 AM  
CO

**Photo # 6834 Erosion & transport of sediment across spur road to location & into a vegetated area**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**Photo # 6835 Erosion & transport of sediment across spur road to location & into a vegetated area**



**Photo # 6836 Erosion & transport of sediment/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**Photo # 6837 Erosion & transport of sediment/insufficient BMP's**



**Photo # 6848 Erosion & transport of sediment/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**Photo # 6849 Erosion & transport of sediment/insufficient BMP's**



**Photo # 6850 Erosion & transport of sediment across road & into a vegetated area/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**Photo # 6851 Erosion & transport of sediment across road & into a vegetated area/insufficient BMP's**



**Photo # 6852 Erosion & transport of sediment across road & into a vegetated area/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**Photo # 6846 Erosion & transport of sediment across road & into a vegetated area/insufficient BMP's**



**Photo # 6845 Erosion & transport of sediment across road & into a vegetated area/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**Photo # 6842 Erosion & transport of sediment across road & into a vegetated area/insufficient BMP's**