

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad

Location ID: 334162



**Photo # 6797 From entrance to location**



**Photo # 6798 From entrance to location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad**  
**Location ID: 334162**



**Photo # 6799 Location**



**Photo # 6801 Location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad

Location ID: 334162



Photo # 6802 Location



Photo # 6807 Location

Inspection Photos  
Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad  
Location ID: 334162



Photo # 6806 Debris



Photo # 6817 Improperly marked deadman

Inspection Photos  
Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad  
Location ID: 334162



Photo # 6818 Unmarked deadman



Photo # 6819 Same unmarked deadman from a different angle

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL PH1 Pad

Location ID: 334162



Photo # 6823 Open ended load line